

CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 19 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [ ]

CORNER IDENTIFICATION - DATE OF VISIT: MARCH 19 77



NORTH 1/4 CORNER OF SECTION 17, 8/19.

CORNER - LEFT AS FOUND [ ] FOUND AND TAGGED [ ] REESTABLISHED OBLITERATED CORNER [X] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Position determined by single proportion between the NW and NE corners of section 17.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 3/4" x 30" Iron Pipe in rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ]

STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

66.55 feet S.W. of a 10" White Oak, I blazed.

9.66 feet EAST of LS tag in rock on West side of fence line, up 2.5 feet.

40.25 feet WEST of LS tag in rock, 10" in diam. & 3' high.

25.0 feet NORTH of fence line East & West.

7.50 feet EAST of fence line North & South.

Copied from Parcel Map 1237  
Surveyed by Stephen L. Jones, L.S. 4298

24/13

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON \_\_\_\_\_ 19 \_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_  
STATEMENT ON BACK OF SHEET: YES [ ] NO [ ]