


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 19 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: MARCH 19 77



WEST 1/4 CORNER OF SECTION 17, 8/19.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Position determined by single proportion between the NW and SW corners of section 17.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 3/4" Iron Pipe in rock mound, 4" up.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

- 42.3 feet EAST of fence line North & South.
- 25.8 feet NORTH of fence line West.
- 59.50 feet WEST of LS tag in flat rock outcrop.
- 147.0 feet S.W. of a 36" White Oak, I blazed.
- 122.0 feet S.E. of an 18" White Oak, I blazed.

Copied from Parcel Map 1237
Surveyed by Stephen L. Jones, L.S. 4298

24/13

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____

STATEMENT ON BACK OF SHEET: YES [] NO []