


CORNER RECORD

COUNTY OF MADERA T. 8 S. R. 19 E. M.D.B.4 MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT JUNE 23 19 78



SOUTH WEST CORNER SECTION 31

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
RESET ALONG TRUE LATITUDE CURVE ON SECOND STANDARD PARALLEL SOUTH ON PRORATION OF GOV'T RE-SURVEY OF 1965 USING SW CORNER SEC. 36 8/18 AND NE COR. SEC. 5 9/19.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
SET 4" x 33" CAST IRON PIPE W/ 2 1/2" BRASS CAP L.S. 2737 - UP 6" IN EARTH & STONE MOUND.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GSI) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)
29.72' SE OF \odot NE COR FENCE POST,
44.00' N. OF FENCE LINE WEST.
30.00' E. OF FENCE LINE NORTH
N 35° 05' 05" E. 53.44' FROM 3/4" I.P. W/ L.S. 2737 PLUG UP 6" AT FENCE CORNER.
100' \pm SW OF LARGE SPRING
500' \pm S. OF COUNTY ROAD 607 E. & W.

J.N. 78-090

F.B. 556/8

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JUNE 27 19 78.
SIGNED: William D. Gentry
L.S. or R.C.E. No.: 2737
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19 ____ AND EXAMINED AND FILED Sept 15 19 78.
BY: A. Brate
TITLE: County Engineer
DOCUMENT No. _____
STATEMENT ON BACK OF SHEET YES NO