


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description SECTION 32 T8S R19E



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |
| Date of Survey | _____ | | |

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAVD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

PER PARCEL MAP 3833 FOR BRIZZOLARA RECORDED IN BOOK 49 PAGE 23

A description of the physical condition of the monument as found and as set or reset: SET 5/8" REBAR & CAP
LS 4261

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyor's Act on _____

Signed _____ P.L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____