


CORNER RECORD

NTY OF MADERA T. 8 R. 19 M.D.B.M MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT SEPT 19 90



S¹/₄ SEC. 33 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

*SOUTH 1/4 COR. SEC. 33 8/19, 78° REBAR, L.S. 5509, L= 45.12
 ESTABLISHED COR. POSITION PER GOV'T PLAT AT MID-POINT IN DEPARTURE
 BETWEEN THE SE & SW CORNERS OF SECTION 33.
 TIES: 1. THE W'LY FORK 9" DIA. OF A WHITE OAK, BEARS N. 65° E. 31.29.
 2. AN 11" DIA. WHITE OAK, BEARS S. 4° W. 71.75'
 3. A 12' DIA. WHITE OAK, BEARS N. 34° W. 50.50'.
 - THE COR. LIES 110' ± EAST & 15' SOUTH OF AN ANGLE POINT IN A FENCE,
 FROM WHICH FENCES RUN N'LY & SW'LY.
 - 1 BLAZED BT'S.*

PHYSICAL DESC

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (M) _____ EASTINGS (M) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM PM 3134 40/67-68

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO