


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of \_\_\_\_\_, California

Brief Legal Description NE COR SEC 34 T8S, R 19E



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

NE COR. SEC. 34/8/19

COPIED FROM  
RS 47/83

3/4" I.P. IN MOUND, NO TAG

I TAG L.S. 4261, PREVIOUSLY SET

ON R-2, L.S. 4546, RESEMBLE MOUND.

TIES 1.) 1/2" W. OAK, N50°E, 39.72', B.T. N51°E, 38.28', 12" OAK.

2.) 6" W. OAK, N50°W, 23.46'

3.) B.T. DOWN, S 25°W, 18" OAK SNAG, 76.56'

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19\_\_\_\_ and examined  
 and filed \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_