


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description SE COR SEC 34 T8S, R19E

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SE COR. SEC. 34 / 8/19

SET $\frac{3}{4}$ I.P. & CAP L.S. 4261 & ROCK MOUND
 TIES 1.) B.T. 1, N76E, 16" W. OAK, 31.02', ORIGINAL
 2.) B.T. 2, N74°30'W, 104.28, 16" W. OAK, ORIGINAL
 3.) TIE, S73W, 10" W. OAK, 15.80'
 4.) TIE, S68E, 11.92', 10" W. OAK

NOTE: B.T. No 142 ALIVE & WELL

COPIED FROM
RS 47/83

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined and filed _____ 19____.

Signed _____ Title _____

County Surveyor's Comment _____