CORNER RECORD

COUNTY OF _MADERA_ T. _85_ R. _20_ E. _M.D.B.&_ MERIDIAN CALIF.

CORNER TYPE: GOV'T. CORNER ( ) MEANDER ( ) RANCHO ( ) CONTROL (✗) OTHER ( )

CORNER IDENTIFICATION --- DATE OF VISIT _10 MAY_ 19 _76_

S¼ Section 2/8/20
A CHISELED X IN A GRANITE STONE 8"×16"×32", 10.60
WEST OF N-S FENCELINE.

CORNER -- LEFT AS FOUND (✗) FOUND & TAGGED ( ) REESTABLISHED OBLITERATED CORNER ( )
         REBUILT ( )

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE & METHOD USED TO IDENTIFY OR
REESTABLISH:

FOUND ORIGINAL BEARING TREE FOR CORNER
SEE BELOW.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED:

LEFT AS FOUND.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ( ) SECOND ( ) THIRD ( )
STATIONS USED: NOS (USC & GS) ( ) STATE ( ) COUNTY ( ) OTHER ( ) STATION_____
STATION_____ ZONE_____ ELEVATION_____ NORTHINGS (Y)_____
EASTINGS (X)_____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME
OR UNDER MY DIRECTION IN CONFORMANCE
WITH THE LAND SURVEYORS ACT ON _____
12 MAY SEN _____ 19 _76_

SIGNED _____ _L.S. 4261_
L.S. or R.C.E. NO. _____
NO. 4261
SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _5-17-76_ AND
EXAMINED & FILED _MAY 17_ 19 _76_
BY: _a. Grote_
TITLE: _County Engineer_

DOCUMENT NO. _76-12-4_
STATEMENT ON BACK OF SHEET
         YES ( )   NO (✗)