


CORNER RECORD

COUNTY OF MADERA T. 8 R. 20 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT oct 1966



SW CORNER SEC. 12 8/20

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" AXLE IN ROCK MOUND
AND TWO B.T.S
ORIGINAL B.T.S FALLEN, BLAZES still visible

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1 1/4" I.P. OVER AXLE

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

FOUND NEW B.T.S:
20" White OAK S 51°E 85.8'
14" " " N 65°30'E 80.1

Copied from RS. 14/114 by RCE 5982

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO