CORNER RECORD		
COUNTY OF Madora 1. 8.5 R 20E MERIDIAN CALIF		
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER		
CORNER IDENTIFICATION - DATE OF VISIT 1-24 19 79		
-34		
CORNER - LEFT AS FOUND TO FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT		
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH		
@ 3/4" I.P. in Rock Mound R.C.E. 13900		
PHYSICAL DESCRIPTION OF MONUMENTS REBUILY OR PERPETUATED		
Jensen: Record of Survey Schwartz		
Schuatte		
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION STATION		
SKETCH: (Include reference tie or witness points, remarks and topo of area)		

9.33° N89° E. 7 , fence Past

	1
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT	AND EXAMINED AND FILED
ON19	84;.
•	TITLE:
L.S. or R.C.E. No.	DOCUMENT No.
	STATEMENT ON BACK OF SHEET
SFA!	YES FIT NO C'I