## **CORNER RECORD**

Meander Pr	A STATE LAND SEMITE LAND SEMIT	COORDINATES(Optional)  OneNAD27  NAD83  NAD83  NAD83 Epoch  Ont. Datum: NGVD29  NADV88
Government Corner Comment Corner Cor	E  N. ontrol	COORDINATES(Optional)  OneNAD27  NAD83  NAD83  NAD83 Epoch  Ont. Datum: NGVD29  NADV88
Government Corner Comment Corner Cor	ontrol E. operty X Zo her N/  El Ve Me  Established   y or procedure used to est	NAD27 NAD83 NAD83 NAD83 NAD83 Epoch  Part. Datum: NGVD29 NADV88 NADV88 NADV88 Repail: National Nationa
Meander Pr Rancho Ot  EC. 33, T.8S., R.20E. Date of Survey 05/13/2015  Corner - Left as found Found and tagged Identification and type of corner found: Evidence used to identification	ontrol	NAD27 NAD83 NAD83 NAD83 NAD83 Epoch ev. ert. Datum: NGVD29 NADV88 Peas. Units: Metric Imperial Reestablished Rebuilt Nabrasablish or reestablish the corner:
Corner - Left as found Found and tagged Identification and type of corner found: Evidence used to identif	Electric Vector Medical Section 1	ev.  ert. Datum: NGVD29 NADV88  eas. Units: Metric Imperial   Reestablished Rebuilt  tablish or reestablish the corner:
Corner - Left as found Found and tagged Identification and type of corner found: Evidence used to identif	Ve Me Bestablished	ert. Datum: NGVD29 NADV88 eas. Units: Metric Imperial Reestablished Rebuilt tablish or reestablish the corner:
Identification and type of corner found: Evidence used to identif	y or procedure used to es	tablish or reestablish the corner:
A description of the physical condition of the manufact of four	d and an act as specie	
A description of the physical condition of the monument as foun	d and as set or reset:	
SET %" REBAR, TAGGED LS 8779.		
	* 1	
SURVEYOR'S STATEMENT		SSED LAND SURVEY
This Corner Record was prepared by me or under my dire	ction in conformance wi	AND DVALL VO
the Land Surveyor's Act on JUNE 23	, 2015 .	No. 8779
Signed P.L.S. or R.C.E	. No.: PLS 8779	CALIFORNIA CALIFORNIA
COUNTY SURVEYOR'S STATEN	IENT	A Secretary and the second sec
This Corner Record was received July 7, 2015	, and ex	amined CONAL LAND SE
and filed August 4, 2015		DAVID M.  McGLASSON
SignedP.L.S. or R.C	.E. No.: PLS 6968	II X No 6069
Title Acting County Surveyor		NO. 0908
County Surveyor's Comment		COFCALIFO
	***************************************	

## **LEGEND** SURVEY MONUMENT (AS NOTED) SET 5/8" REBAR, LS 8779 0 SCALE 1"=60" DIMENSION POINT (NOTHING FOUND OR SET) (...)(1) BK. 16, PG. 53, M.C.R. (M) **MEASURED** PROPERTY LINE ADJOINING PROPERTY LINE RIGHT-OF-WAY CENTERLINE ¾" IRON PIPE LS 2931 (5 48.00) (1) (4) (N36'30'00"E 546.00')(1)(M) $(150.00^{\circ})(1)(M)$ LILLEY MOUNTAIN DR. SET %" REBAR LS 8779 (150.00')(1)(M)

## **CORNER RECORD**

LOT 1379 OF YOSEMITE LAKES PARK, RECORDED IN BOOK 16 OF MAPS AT PAGE 53, M.C.R. LOCATED IN SECTION 33, T8S, R20E, M.D.B.&M.

> LAND SUR DEWITH No. 8770

> > 150.00')(1)

LOT 1377

¾" IRON PIPE LS 2931, BENT

LOT 1378

(\$53°30'00"E 300.00')(1) \$52°53'23"E 300.87'

¾" IRON PIPE LS 2931

LOT 1379

¾" IRON PIPE LS 2931

LOT 1380

JONES SNYDER & ASSOCIATES P.O. BOX 2292, OAKHURST, CA 93644 (559)683-7661 WWW.JSSURVEYING.COM

DATE: JUNE 23, 2015 JOB NO: 15-146

DWG FILE: 15-146CR DRAWN BY: RJD