


CORNER RECORD

Document Number R.O.F.S. BK. 44 P. 6

City of _____ County of _____, California

Brief Legal Description SECTION 1 TOWNSHIP 8 E, RANGE 18 S. CENTER SECTION



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey MARCH 1995

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET P.K. NAIL & TAG L.S. 4261

A description of the physical condition of the monument as found and as set or reset: _____

TIES: ① S 66-03-07 W, 33.68 TO NAIL IN ROCK
② N. 80 W, 9.01 TO P.K. IN ROCK

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____

