


MARIPOSA

CORNER RECORD

COUNTY OF TOWNSHIP 8 SOUTH, RANGE 18 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [ ]

CORNER IDENTIFICATION - DATE OF VISIT: APRIL 19 73



NORTH 1/4 CORNER OF SECTION 1, 8/18.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [ ] REESTABLISHED OBLITERATED CORNER [ ] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found BLM brass cap monument.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ]

STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION \_\_\_\_\_ STATION \_\_\_\_\_


ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

N 21°19'E 36.6 feet 23" scribed Oak

S 74°E 40.26 feet 23" Oak stump



Copied from Record of Survey of Buchanan Dam Boundary  
Surveyed by James E. McPheeters, L.S. 2854

21/86-92

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON \_\_\_\_\_ 19 \_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_.

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_

STATEMENT ON BACK OF SHEET: YES [ ] NO [ ]