## CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RAN	GE 18 EAST, M.D.B.&M. CALIFORNIA
CORNER TYPE: GOV'T. CORNER 😾 MEANDER 🗌	RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT: APRIL	<sub>19</sub> 73
<b>P</b>	
NORTH 1/4 CORNER OF	F SECTION 23, 8/18.
	·
	1
ORNER - LEFT AS FOUND 🔀 FOUND AND TAGGED 🗌 REEST	TABLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND MET	HOD USED TO IDENTIFY OR REESTABLISH
Found BLM brass cap monument.	
round bum brass cap monument.	
HYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATE	ED
	•
ALIFORNIA COORDINATE SYSTEM ORDER: FIRST	SECOND THIRD
TATIONS USED: NGS (USC & GS) STATE	
ONE ELEVATION NORTH	HINGS (Y) ZASTINGS (X)
KETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMAF	DVS AND MODO OF AREA
WICH. (INCLUDE REFERENCE THE OR WITHESS FOIRIS, REPAR	CO AND TOPO OF AREA)
TIES	SE THE
	OF THE WA
N 23°20'E 86.13 feet 33" scr	ribed Oak
	(S. N. P. O.)
N 79°30'W 169.95 feet 33" scr	ribed Oak $\int_{0}^{\infty} S = s \cos \left( s \cos \left( \frac{\pi}{2} \right) \right)$
	The state of the s
	T.O.S R.O.E.
	CROPSTRAL SURVEY AND MANAGER
	ON TRAL SOLLO
· · ·	AND MAN
·	
Copied from Record of Survey of E	Ruchanan Dam Roundary
Surveyed by James E. McPheeters,	954
ban vegeta signatura de memberes p	21/86-92
SURVEYOR'S CERTIFICATE	
SURVETORS CERTIFICATE HIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	COUNTY SURVEYOR'S CERTIFICATE
IRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S	THE CORNER RECORD WAS RECEIVED 19
CT ON19	AND EXAMINED AND FILED19
	BY:
SIGNED:	
.S. or R.C.E. No:	
SEAL	DOCUMENT NO: STATEMENT ON BACK OF SHEET: YES NO
** <del></del>	