CORNER RECORD

COUNTY OF Madera T. 85 R. 2		MERIDIAN C
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO	CONTROL OTHER	
CORNER IDENTIFICATION — DATE OF VISIT 4 Sep.	19 / 4	
1.36		
CORNER — LEFT AS FOUND FOUND AND TAGGED REES	STABLISHED OBLITERATED CORNER	REBUILT 🔀
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD US	SED TO IDENTIFY OR REESTABLISH	
Found Rock Mound w/Ties to	two bearing tre	es & fence
per Madera Co. F.B. 200, Pg. 6	- dated 14 5ah	53
per madera co. 1.6. 200, pg. a	5 daica 14 feet	,.,
Ties were checked & found to	be acceptable.	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-	
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	1 6	. 1
Set 12" Galvanized Iron Dipe in	n center of exis	TING
rock mound. Up 1.5 w/ L5 tag.	7854	
rock mound. Up 1.5 W/ 25 Tag		
		· · · · · · · · · · · · · · · · · · ·
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND	THIRD	
		STATION
ZONE BLEVATION NORTHINGS (Y)	trans-1	
SKETCH: (Include reference tie or witness points, remarks and topo	of area)	
distriction (management of the control of the contr		
cat 11" salv sine 1.		
set 1½"galv. pipe in rock mound. Tagged	· · · · · · · · · · · · · · · · · · ·	
rock mound. lagged	63 18" Engelme	in Jah
rock mound. Tagged LS 2854. Up 15	w/blaz	e
	5 ⁹	
,' •, 10	•	
, BE		
"England Oak		A
		/\
blaze. (- 742' - 7	x wire fence	//\
~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	x wire tence	// \
•		M
		1.
		N
	·	17 " = 50"
		1 = 20
SURVEYOR'S CERTIFICATE	COUNTY SURVEY	OR'S CERTIFICATE
PRINER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEI	n. + 11
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT	AND EXAMINED AND FILED	Oct 23 18 74
PINCOUPIN IN CORPORDANCE WITH THE LAND SURVEYURS ALL	MIND EXAMINED AND FILED.	
ON SEPT 16 1974	BY: Ull	et O Good
In - of the second	BY: all	t En
In - of the second	Link	to Engine

SEAL

YES [

STATEMENT ON BACK OF SHEET