


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description N 1/4 COR. SEC 2 T 8 S R 21 E



### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

N 1/4 CORNER SECTION 2 8/21

FOUND NO EVIDENCE OF ORIGINAL CORNER MONUMENT OR ACCESSORIES. RE-ESTABLISHED CORNER POSITION BY SINGLE PROPORTIONATE MEASURE. SET 5/8" DIA. REBAR, 30" LONG WITH PLASTIC CAP, UP 6"

#### TIES:

1. A LIVE OAK, 9" DIA., BEARS N 17°38' E, 12.98' - I BLAZED.
  2. A LIVE OAK, 8" DIA., BEARS S 55°53' E, 20.65' - I BLAZED.
  3. A LIVE OAK, 7" DIA., BEARS S 87°47' W, 60.38' - I BLAZED.
  4. S 86° W, 91.17' TO A GULCH BEARING S 7° W & N 21° E.
- DISTANCES ARE HORIZONTAL TO NAILS & TAGS, LS 5509 IN SIDE-CENTER OF TREES.

COPIED FROM  
RS 48/45-46

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_