


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description NW 1/4 COR. SEC. 2 T8S R21E



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

NW 1/16 CORNER SECTION 2 8/21

SET 5/8" REBAR, 30" LONG WITH PLASTIC CAP, UP 12". BUILT ROCK MOUND 1' X 2' X 1' HIGH AROUND MOUNUMENT.

TIES:

1. A CHISELED CROSS IN A ROCK 1' X 2' X 1' HIGH BEARS N 17°33'32" E, 31.33'.

COPIED FROM
RS 48/45-46

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____

