


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of MADERA, California

Brief Legal Description C-S 1/4 COR SEC 2 T8S R21E



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

C-S 1/4 CORNER SECTION 2 8/21

SET 5/8" REBAR, 30" LONG WITH PLASTIC CAP, UP 6".

#### TIES:

1. A LIVE OAK, 4" DIA., BEARS S 82°E, 6.37' - I BLAZED.
2. A PONDEROSA PINE, 6" DIA., BEARS N 42°E, 30.98' - I BLAZED.
3. A CHISELED CROSS IN A ROCK, FLUSH IN THE CENTER OF A DIRT ROAD, BEARS S 82°W, 24.60'.  
 - DISTANCES ARE HORIZONTAL TO NAILS & TAGS, LS 5509 IN SIDE-CENTER OF TREES.

*COPIED FROM  
RS 48/45-40*

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_