


CORNER RECORD

Document Number _____

City of _____

County of MADERA, CaliforniaBrief Legal Description W 1/16 COR. SEC. 2 T8S, R21

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

W 1/16 CORNER SECTION 2 8/21

SET 5/8" REBAR, 30" LONG WITH PLASTIC CAP, UP 6".

TIES:

1. A BLACK OAK, 6" DIA., BEARS S 75° E, 24.14' - I BLAZED.
 2. A BLACK OAK, 18" DIA., BEARS S 43° W, 43.95' - I BLAZED.
 3. A BLACK OAK, 16" DIA., BEARS N 50° W, 32.95' - I BLAZED.
 4. S 43° W, 29' TO A FENCE RUNNING NW & SE
 5. N 55° E, 65' +/- TO A DIRT ROAD RUNNING NW & SE
- DISTANCES ARE HORIZONTAL TO NAILS & TAGS, LS 5509 IN SIDE-CENTER OF TREES.

*COPIED FROM
RS 48/45-46*

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____