


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description W 1/4 COR. SEC. 2 T8S R21E



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

W 1/4 CORNER SECTION 2 8/21

FOUND NO EVIDENCE OF ORIGINAL CORNER MONUMENT OR ACCESSORIES. RE-ESTABLISHED CORNER POSITION ON LINE BETWEEN THE NW & SW CORNERS OF SECTION 2 AT RECORD DISTANCE FROM ORIGINAL TOPO CALL TO GULCH 46.20' NORTH. SET 5/8" DIA. REBAR, 30" LONG WITH PLASTIC CAP, UP 6". BUILT 1' DIA. ROCK MOUND AROUND MONUMENT.

TIES:

1. A NAIL & TAG, LS 5509 IN A ROCK 1 1/2' X 3' X 1 1/2' HIGH, BEARS N 81°02'35" E, 43.93'.
2. A CHISELED CROSS IN A ROCK 1 1/2' X 3' X 1 1/2' HIGH, BEARS N 1° 51'19" W, 68.67'.
3. A NAIL & TAG, LS 5509 IN A ROCK 1 1/2' X 2' X 1 1/2' HIGH, BEARS N 54°11'39" W, 86.49'.

— FOUND A 1 1/2" D.D.I.P., RCE 21650 S 69°30'34" W, 33.61' FROM THE CORNER — NOT ACCEPTED.

COPIED FROM
RS 48/45-46

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____

