CORNER RECORD		100
countr of Madera . 8 S 21 E. M.D.B.	& M. MERIDIAN CALIFO	ZN61
CORNER IDENTIFICATION - DATE OF VISIT March 1 19 84		
	•	
The northwest corner of section 3 8/21.		
(common to sections 33 & 34 7/21 and sections	3 & 4 8/21)	
CORNER LEFT AS FOUND TO POUND AND TAGGED TO REESTABLISHED OBLITERATED CON	HER RESULT	
PHYSICAL DESCRIPTION OF CORNEX FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REISTA		
Found and Accepted: A GLO iron pipe, 1 3/4" O.D., up 6", ir		
rock mound, with a 2 1/2" dia. brass cap, stamped for the co	when the date and the	i
GLO logo per field notes of Dupree R. Averill, U.S. Deputy S		
and rogo per riend notes or pupies k. Averir, o.s. beputy a	diveyor, 1922.	
	•	-
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Left the monument as found.		
		-
	· · · · · · · · · · · · · · · · · · ·	
•		
	-	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD		
STATIONS USED: NGS (USC & GS) STATE CDUNTY OTHER STATION ZONE ELEVATION NORTHINGS (Y)		
ZONE ELEVATION NORTHINGS (Y)	EXSTINGS (X)	
SKETCH: (Include reference tie or witness points, remarks and topo of area)		
Corner Ties:	Cap Inscription	
7 7 7 0 1 7 0 7 7 1		
1. A Live Oak, 7.8" dia., bears S 30° 45' E, 22.55'.	T 7 S R 21 E	
2 2 Dinam Dina 14 70 315	s 33 + s 34	
2. A Digger Pine, 14.7" dia., bears S 12° 24' W, 45.75'.	S 4 I S 3	-
2 A Time Only 6 Eff dia home N E79 251 N 12 071	T 8 S	
3. A Live Oak, 6.5" dia., bears N 57° 25' W, 12.07'.	1922	
4. A Live Oak, 6.2" dia., bears N 54° 43' E, 34.32'.		
4. H bive out, 0.2 dia., bears it 34 45 b, 34.32 .		
	•	
fence line runs north and south from the corner.		
Land Land Falls for the boddin Lion the collicia		
fence corner with fences running north, south and west		
ies 6' north of the corner.		
fence corner with fences running SE'ly and SW'ly lies	A-13	
south of the corner.	F.B. 26/45	
	Mon. Bk. 3/3	
	Job No. 83-20	
O LAND C	(Continued on back)	
SUPPLICATION CONTINUES COU	MTY SURVEYOR'S CIRTIFICATE,	
THIS CORNER RECORD THE PREPARED BY HE OR CURDER MY THE CORNER RECOR	WAS ESCENTED DO 198	Z
DIRECTION IN CONFORMANCE WITH THE LAND SHEETINGS ACT AND EXAMINED AN		1
OH AUHEN 19 EQ	someway (1.4) Hours	12
Time:		
SIGNED FAREWARD LEGISLA CARLO DOCUMENT No.		
Li water military 4689	T AL FURNIT	
LS 4689 STATUMENT ON BAC	aurancei Y21.1⊽1 MO.F	٦
To the second se		j.
OF CALIFO		
The state of the s		

Bearings are to the center of trees at the base. Distances are horizontal to a nail are tag (stamped LS 4689) driven into the side center of the root crown.

082140070Va