


CORNER RECORD

Document Number _____

City of _____ County of MADERA, California

Brief Legal Description S 1/4 COR SEC 3 T 8 S R 21 E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

S 1/4 CORNER SECTION 3 8/21

SET 5/8" DIA. REBAR, 30" LONG WITH PLASTIC CAP, UP 6" IN THE CENTER OF A FOUND 2' DIA. ROCK MOUND, FLUSH.

TIES:

1. A WHITE OAK SNAG, 20" DIA. WITH OLD HEALED BLAZE, BEARS S 58° E, 11.51'.
[A WHITE OAK, 16" DIA. BEARS S 64° E, 11.88']
 2. A WHITE OAK, 11" DIA., BEARS N 7° E, 16.60' - I BLAZED.
 3. A WHITE OAK, 8" DIA., BEARS S 5° E, 30.94' - I BLAZED.
 4. A WHITE OAK, 18" DIA., BEARS N 62° W, 11.08' - I BLAZED.
- DISTANCES ARE HORIZONTAL TO NAILS & TAGS, LS 5509 IN SIDE-CENTER OF TREES.

*COPIED FROM
RS 48/45-46*

as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____