


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of MADERA, California

Brief Legal Description SW COR SEC 3 T 8 S R 21 E



### CORNER TYPE

- |                   |                          |          |                          |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control  | <input type="checkbox"/> |
| Meander           | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho            | <input type="checkbox"/> | Other    | <input type="checkbox"/> |
| Date of Survey    | _____                    |          |                          |

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SW CORNER SECTION 3 8/21

FOUND 2" IRON PIPE, UP 11" IN A 2' DIA. ROCK MOUND, FLUSH WITH THE GROUND.

#### TIES:

1. A PINE, 14" DIA., BEARS S 73°W, 12.56'.
2. A PINE, 20" DIA., BEARS N 14°E, 45.08'.
3. A BLACK OAK, 16" DIA., BEARS N 59 1/2° E, 50.74'.  
[A BLACK OAK, 12" DIA., BEARS N 52°E, 50.16']
4. A BLACK OAK, 26" DIA., BEARS S 46 1/4° W, 91.72'.  
[A BLACK OAK, 12" DIA., BEARS S 43°W, 95.04']

*COPIED FROM  
RS 48/45-46*

as set or reset: \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_