


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 21 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [ ] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [ ]

CORNER IDENTIFICATION - DATE OF VISIT: JAN 19 85



E 1/4 COR SEC 4 8/21

CORNER - LEFT AS FOUND [ ] FOUND AND TAGGED [ ] REESTABLISHED OBLITERATED CORNER [ ] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1" I.D.I.P. UP 10", IN CAIRN

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET 5/8 REBAR W/ALUMINUM CAP 3" DIAMETER

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ]

STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

ON N-S FENCE  
63.0' N1 OF X IN FENCE TO N & W  
N 21° W 19.62' TO A SHINGLE NAIL UP 6"  
ON W/S OF 6" LIVE OAK

COPIED FROM RECORD OF SURVEY FOR DON WILLIAMS BY  
DOUG BREADAHL L.S. 4509

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

\_\_\_\_\_ 19 \_\_\_\_\_

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_  
STATEMENT ON BACK OF SHEET: YES [ ] NO [ ]