


CORNER RECORD

Agency Index _____

Document Number _____

City of _____ County of _____ Madera _____, California

Brief Legal Description East 1/4 Corner Section 11, T.8S., R.21E., M.D.B.&M.**CORNER TYPE****COORDINATES (Optional)**

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey March 8, 2022

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902PLS Act Ref.: 8765(d) 8771 8773 Other:Corner/ Left as found Established Rebuilt Pre-ConstructionMonument: Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

 See sheet #2 for description(s):

Set 3/4" iron pipe up 3" in , PLS7061 tag by single proportion.
 Set nail & tin in a 4" live oak, North 22.5° East, 8.30'.
 Set nail & tin in a 4" live oak, South 82.5° East, 6.65'.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 24, 2022Signed Travis Dams P.L.S. or R.C.E. No. 7061**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received Aug. 15th, 2022and examined and filed Aug. 17th, 2022.Signed Garland R. Shaw P.L.S. or R.C.E. No. 4837Title CO-ACTING COUNTY SURVEYOR

County Surveyor's Comment

No comments!