

# CORNER RECORD

Agency Index \_\_\_\_\_


Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of Madera, California

Brief Legal Description South 1/4 Corner Section 11, T.8S., R.21E., M.D.B.&M.

### CORNER TYPE

### COORDINATES (Optional)



X

- Government Corner     Control  
 Meander                       Property  
 Rancho                             Other

Date of Survey March 8, 2022

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units     Metric             U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.:     8765(d)             8771             8773             Other:

Corner/  
Monument:     Left as found             Established             Rebuilt             Pre-Construction

Found and tagged             Reestablished             Referenced             Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found original 40" (16") black oak , North 87° West, 66 links. Set 3/4" iron pipe up 3" in stone mound, PLS7061 tag South 87° East, 44.89' from tree center.

Set nail & tin in a 40" black oak, North 87.0° West, 42.48'.

Set nail & tin in a 12" white oak, North 22.5° West, 29.07'.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 24, 2022

Signed Travis Davis P.L.S. or R.C.E. No. 7061

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 15<sup>th</sup>, 2022

and examined and filed April 17<sup>th</sup>, 2022

Signed Garland R. Shaw P.L.S. or R.C.E. No. 4837

Title Co-Acting County Surveyor

County Surveyor's Comment

No Comments!

