


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description W 1/4 Cor SEC 11 T8S R21E



### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

W 1/4 CORNER SECTION 11 8/21

SET 5/8" REBAR, 30" LONG WITH PLASTIC CAP, UP 6" AT RECORD BEARING AND DISTANCE FROM FOUND ORIGINAL BEARING TREE. BUILT 2' DIA. X 1' HIGH ROCK MOUND AROUND MONUMENT.

#### TIES:

1. A WHITE OAK, 14" DIA., BEARS N 77°E, 26.40'.  
 [A WHITE OAK, 6" DIA., BEARS N 77°E, 26.40']
  2. A WHITE OAK, 36" DIA., WITH OLD BLAZE FACING CORNER, BEARS N 11 3/4°E, 38.09'.
  3. A CHISELED CROSS IN A ROCK 3' X 3' X 2' HIGH, BEARS N 72° E, 12.44'.
  4. A NAIL AND TAG, LS 5509, IN A ROCK 4' X 5' X 3' HIGH, BEARS S 45° E, 48.22'.
  5. A BLACK OAK, 14" DIA., BEARS WEST, 10.04'
- THE CORNER LIES 23.7' NORTH OF A GULCH BEARING SE & NW.  
 - DISTANCES ARE HORIZONTAL TO NAILS & TAGS, LS 5509 IN SIDE-CENTER OF TREES.

COPIED FROM  
RS 48/45-46

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_