


CORNER RECORD

COUNTY OF MADERA T. 8 R. 21 MERIDIAN CALIFORNIA  
CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
CORNER IDENTIFICATION - DATE OF VISIT \_\_\_\_\_ 19\_\_\_\_



W 1/4 COR. SEC. 17 1/2

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FD. 1 1/2" IP+TAG RCE 5982 + TABLE LEG IN ROCK MD.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM, ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

BEARING TREES FROM CORNER:  
24" W. O. S16° W. 110.22' (ORIG)  
12" L. O. N57° E 13.0' (NEW)  
20" W. O. N48 1/2° W 26.5' (NEW)

COPIED FROM PM 118 BY MCKEE RCE 5982 + RIS B. 17 p. 67

<p><b>SURVEYOR'S CERTIFICATE</b> THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____</p> <p>SIGNED: _____ I.S. or R.C.E. No.: _____</p> <p>SEAL</p>	<p><b>COUNTY SURVEYOR'S CERTIFICATE</b> THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED BY _____ 19____</p> <p>TITLE: _____</p> <p>DOCUMENT No. _____</p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input type="checkbox"/></p>
--	---