


**CORNER RECORD**

COUNTY OF MADERA    TOWNSHIP 8 SOUTH,    RANGE 21 EAST, M.D.B.&M.    CALIFORNIA

CORNER TYPE:    GOV'T. CORNER     MEANDER     RANCHO     CONTROL     OTHER

CORNER IDENTIFICATION - DATE OF VISIT: \_\_\_\_\_ 19 74



W 1/4 cor. Sec 22 8/21

CORNER - LEFT AS FOUND     FOUND AND TAGGED     REESTABLISHED     OBLITERATED CORNER     REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Corner falls in Creek.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

1" I.P. L.S. 2737 IS WITNESS. Corner Bears N 14° 28' E 9.10' from 1/4 cor. Driven in Boulder

CALIFORNIA COORDINATE SYSTEM ORDER:    FIRST     SECOND     THIRD

STATIONS USED:    NGS (USC & GS)     STATE     COUNTY     OTHER     STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

8" LIVE OAK (RCE 5982 NE FACE)  
N 60° 28' W 66.95'

5" LIVE OAK (RCE 5982 NWRACE)  
N 48° 51' E 38.17'

4" LIVE OAK (RCE 5982 N FACE)  
S 85° 16' 20.11'

C. S. McKee

COPIED FROM OLD MADERA COUNTY GOVERNMENT MONUMENTS BOOK.

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

\_\_\_\_\_ 19 \_\_\_\_\_

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_  
STATEMENT ON BACK OF SHEET:    YES     NO