


CORNER RECORD

Document Number _____

City of _____

County of MADERA, CaliforniaBrief Legal Description SW Cor SEC 23 T 8S R 21E

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SW CORNER SECTION 23 8/21

FOUND A 5/8" DIA. REBAR WITH A PLASTIC CAP STAMPED LS 4298,
 UP 6" IN A 3' DIA. X 1' HIGH ROCK MOUND.

TIES:

1. A WHITE OAK SNAG, 50" DIA. WITH BLAZE AND SCRIBING,
 BEARS N 63°E 215.16'.
 [A WHITE OAK 38" DIA., BEARS N 63°E, 215.16'.]
 2. A WHITE OAK, 19" DIA., BEARS N 66°30'16" W, 116.48'.
 3. A WHITE OAK, 12 1/2" DIA., BEARS S 38°13'35" W, 90.53'.
 4. A WHITE OAK, 11" DIA., BEARS S 54°26'24" E, 160.20'.
 5. A FORKED WHITE OAK, 20" DIA., BEARS N 42°45'47" E, 160.87'.
 6. A CREEK RUNNING NORTH & SOUTH BEARS WEST 30' +/-.
- FOUND A 1" IRON PIPE IN ROCK MOUND, LS 4261, S 7°34'52" E,
 135.75' - NOT ACCEPTED.

*COPIED FROM
 RS 48/45-46*

as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined
 and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____