


# CORNER RECORD

COUNTY OF Madera T. 8 S. R. 21 & 22E. M.D. CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT April 5 19 88



Quarter Corner for Sections 25 and 30

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH No original evidence was found despite diligent search. Corner set by single proportion measurement.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Installed a 3/4 x 30 inch iron pipe in the earth with a 1" aluminum cap stamped for the corner and LS4126. It is on a West slope about 7 feet West of a N/S fence and 38 feet South of E/W fence. From which bears a 30" diameter white oak S1°W, 8.78 feet, blazed and scribed for the corner and a 6" liveoak, in a coppice, N85°E, 12.11 feet, blazed and scribed for the corner. Set USFS K-tag and Survey Monument signs.


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON April 5 19 88

SIGNED: *[Signature]*

L. or R.C.E. No. \_\_\_\_\_



SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED 5/12 19 88 AND EXAMINED AND FILED

BY: *[Signature]*

TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO