


# CORNER RECORD

COUNTY OF Madera T. 8 S. R. 21 E. M. D. M. D. MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION — DATE OF VISIT April 12 19 88



Quarter Corner for Sections 25 and 26

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH No original evidence was found despite deligent search. Corner set by single proportion measurement.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Installed a 3/4 x 30 inch iron pipe in the earth with a 1" aluminum cap stamped for the corner and LS4126. It is on a Southeast slope at the West edge of a large flat dry meadow. From which bears a 10" diameter white oak S54°E, 13.51 feet, blazed and scribed for the corner, and a 8" diameter white oak N64°E, 60.47 feet, blazed and scribed for the corner. Set USFS K-tag and Survey Monument signs.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
 DIRECTOR'S SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

SIGNED: [Signature] 19 88

NO. 4126

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED 5/12 19 88  
 AND EXAMINED AND FILED [Signature]

BY: [Signature]

TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET: YES  NO