


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 21 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



NORTHWEST CORNER SECTION 27 8/21

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1" IRON PIPE UP 5" IN ROCK MOUND TAGGED L.S. 2737

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

WEST 4.50' NORTH-SOUTH FENCE LINE
SOUTH 36.90' FENCE CORNER N-S/E-W

- A. A 28" WHITE OAK 59' TO SE, WITH POSSIBLE HEALED BLAZE, I BLAZED BELOW SAID BLAZE,
B. A 14" WHITE OAK 48.40' TO NORTH BY NORTHEAST WHICH I BLAZED.
C. A 30" AT BASE L. OAK CLUSTER, 30.40' TO SOUTHWEST, (TO NORTHERN TRUNK OF SAID CLUSTER WHICH I BLAZED.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES [] NO []