CORNI	ER RECORD /
COUNTY OF MADERA T. 85	ER RECORD R. 2/E M.D.B & MERIDIAN CALIF.
	R () RANCHO () CONTROL () OTHER ()
CORNER IDENTIFICATION DATE OF VISIT _ 20 , 2/	
N.E. CORNER SEC. 29	
REBUILT ()	GED () REESTABLISHED OBLITERATED CORNER ()
PHYSICAL DESCRIPTION OF CORNER FOUND: EVI REESTABLISH: 21/2" BRASS CAP, STA	IDENCE & METHOD USED TO IDENTIFY OR MICHON SEC. 20 121 T852/1E. 29 128
4.5.601. SURNEY, 1953.	29/28
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT	OR PERPETHATED.
LEFT AS F	_
LEFT AS F	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRS STATIONS USED: NOS (USC & GS) () STATE STATION ZONE ELEVATION EASTINGS (X)	E () COUNTY () OTHER () STATION
	S POINTS, REMARKS AND TOPO OF AREA)
THE STATE OF WILKES	55 POINTS, REMARKS AND TUPU OF AREA)
	X
•	X North
	NORTH
	Î
	*
— X — x — x — x — x	21/2" BR. CAP. U.S. GOV. 1953
	O. B. WEST TO FENCE POST
	7.6 NO. TO FENCE POST
CORNER LIES IN FENCE	INTERSECTION, OAK GRIVE AROUND IT.
	Tence So.
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE	THE CORNER RECORD WAS RECEIVED 7-2-76 AUD EXPANSE
THE THE ALAND SURVEYORS ACT ON 15	TITLE: County Engineer
L. M. JERGSER Jensey	DOCUMENT NO. 76-15-3
S. or R.C.E. (16: 12.5.426)	STATEMENT ON BACK OF SHEET YES () NO (*)
NO. 4261 PIE OF CALIFORNIE	
OF CALIFORN	