COUNTY OF MADERA T. 85, R.	Y/E. MERIDIAN CALIF.
CORNER TYPE: GOV"T CORNER [] MEANDER []	RANCHO [] CONTROL M OTHER[]
CORNER IDENTIFICATION DATE OF VISIT	15 Oct. 19 75
30 20 - 6/4 - 30-8-71	
REBUILT [] — SET	ED [] REESTABLISHED OBILTEPATED CORNER []
PHYSICAL DESCRIPTION OF CORNER FOUND; EVID REESTABLISH: SET CENTER 1/4 OF SE	DENCE & METHOD USED TO IDENTIFY OR SCTION 30 BY PROPERTION
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT  SET 3/4" IRON PIPE TAGGE D L.S.	4761, ON SMALL RIDGE
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST STATIONS USED: NOS (USC & GS) [] STATE STATION ZONE ELEVATION	[] COUNTY [] OTHER [] STATION
EASTINGS (X)	
SKETCH: (INCLUDE REFERENCE TIE OR WITNESS	S POINTS, REMARKS AND TOPO OF AREA)
	102
	ASPECT NORTH
	ASPECT NORTH
	4" IRON PIPE, L.S. 4261 ON RIDGE
PATINE DAK 3 0	43.5
¥ 3€ 8"2.01	SE G"LIVE ORK.
SURVEYOR'S CERTIFICATE  THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEORS ACT ON Oct.	COUNTY SURVEYOR'S CERTIFICATE  THE CORNER RECORD WAS RECEIVED 10/17  19 75 AND BRAMINED AND FILED 10-20  BY: County Engineer
	1
SISED LAND SISNED.	DOCUMENT NO. 75-33-01
SIGNED: 2.5.4761	DOCUMENT NO. 75-33-0; STATEMENT ON BACK OF SHEET YES [] NO M
SEAL	STATEMENT ON BACK OF SHEET
SEAL X	STATEMENT ON BACK OF SHEET
SEAL	STATEMENT ON BACK OF SHEET