


CORNER RECORD

COUNTY OF MADERA TOWNSHIP **8** SOUTH, RANGE **21** EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: MAY 19 47



WEST ¼ CORNER OF SECTION 30, 8/21.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Reestablished corner by Single Proportion between the NW corner of section 30 & the SW corner of section 31.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" Iron Pipe in rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

- N 11°00'E , 16 feet to a 5" Live Oak.
- N 14°30'W , 42 feet to a 24" Live Oak.
- S 52°00'E , 68 feet to an 8" forked Live Oak.

**Copied from Record of Survey for R. L. Greaves.
 Surveyed by Chas. O. Price, R.C.E. 4263**

VOL. 6 PAGE 57

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
 STATEMENT ON BACK OF SHEET: YES NO