


**CORNER RECORD**

COUNTY OF MADERA    TOWNSHIP    **8**    SOUTH,    RANGE    **21**    EAST, M.D.B.&M.    CALIFORNIA

CORNER TYPE:    GOV'T. CORNER     MEANDER     RANCHO     CONTROL     OTHER

CORNER IDENTIFICATION - DATE OF VISIT:    MAY    19 47



**NORTHWEST CORNER OF SECTION 31, 8/21.**

CORNER - LEFT AS FOUND     FOUND AND TAGGED     REESTABLISHED OBLITERATED CORNER     REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Reestablished corner by Single Proportion between the NW corner of section 30 & the SW corner of section 31.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" Iron Pipe in rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER:    FIRST     SECOND     THIRD

STATIONS USED:    NGS (USC & GS)     STATE     COUNTY     OTHER     STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

**TIES**

N 27°30'E , 42 feet to a 14" White Oak.  
 N 86°00'E , 63 feet to an 8" White Oak.  
 S 75°00'W , 61 feet to an 8" White Oak.

Copied from Record of Survey for R. L. Greaves.  
 Surveyed by Chas. O. Price, R.C.E. 4263

VOL. 6    PAGE 57

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON \_\_\_\_\_ 19\_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_.

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_  
 STATEMENT ON BACK OF SHEET:    YES     NO