

CORNER RECORD

COUNTY OF MADERA T. 8 S. R. 21 E. M.D.B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT APRIL 19 79



NORTHWEST CORNER SECTION 33 8/21

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3/4" Iron Pipe in mound Tagged L.S. 2741

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES

S 80° E 24.83 feet to a P.K. nail in granite boulder.
 N 28° W 8.20 feet to a P.K. nail in rock.

Copied from record of survey for Vinnard & Jungmeyer by L.M. Jensen
 L.S. 4261

<p align="center">SURVEYOR'S CERTIFICATE</p> <p>THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____.</p> <p>SIGNED: _____</p> <p>L.S. or R.C.E. No.: _____</p> <p align="center">SEAL</p>	<p align="center">COUNTY SURVEYOR'S CERTIFICATE</p> <p>THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____ BY: _____ TITLE: _____</p> <p>DOCUMENT No. _____</p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input type="checkbox"/></p>
---	---