

**CORNER RECORD**

COUNTY OF MADERA T. 8 S. R. 21 E. M.D.B. & MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION -- DATE OF VISIT APRIL 19 79



WEST 1/4 CORNER SECTION 33 8/21

CORNER -- LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3/4" Iron Pipe in mound Tagged L.S. 2741

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

**TIES**

N 50° W      17.08 feet to a P.K. nail in rock.  
 S 32° E      39.29 feet to a 4" White Oak.

Copied from Record of Survey for Vinnard & Jungmeyer by L.M.Jensen  
 L.S. 4261

<p align="center"><b>SURVEYOR'S CERTIFICATE</b></p> <p>THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____.</p> <p>SIGNED: _____                  L.S. or R.C.E. No. _____</p> <p align="center">SEAL</p>	<p align="center"><b>COUNTY SURVEYOR'S CERTIFICATE</b></p> <p>THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____ BY _____ TITLE: _____</p> <p>DOCUMENT No. _____</p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input type="checkbox"/></p>
--	--