


CORNER RECORD

COUNTY OF Madera T. 8 S. R. 21 E. M. D. MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT April 6 19 88



Quarter Corner for Sections 25 and 36

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH No original evidence was found despite diligent search. Corner set by single proportion measurement.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Installed a 3/4 x 30 inch iron pipe in the earth with a 1" aluminum cap stamped for the corner and LS4126. It is on a North slope. From which bears a 23" diameter white oak N49°W, 30.15 feet, blazed and scribed for the corner, and a 13" diameter liveoak S28°E, 36.68 feet, blazed and scribed for the corner. Set USFS K-tag and Survey Monument signs.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON April 6 19 88

SIGNED: [Signature]
 L. or R.C.E. No. 4126



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED 5/12 19 88
 AND EXAMINED AND FILED [Signature]
 BY: [Signature]
 TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO