


CORNER RECORD

COUNTY OF Madera T. 8 S. R. 21 E. M.D. CALIFORNIA MERIDIAN

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION - DATE OF VISIT April 5 19 88



Quarter Corner for Sections 35 and 36

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  RESULT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH No original evidence was found despite diligent search. Corner set by single proportion measurement.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Installed a 3/4 x 30 inch iron pipe in the earth with a 1" aluminum cap stamped for the corner and LS4126. It is on a Northeast slope about 120 feet East of a N/S fence. From which bears a 15" diameter liveoak N58°E, 23.79 feet, blazed and scribed for the corner. Set USFS K-tag and Survey Monument signs.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

LAND SURVEYORS CERTIFICATE  
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON APRIL 5 19 88  
SIGNED Charles Victor Strora  
L. S. or R. C. E. J. No. 41201  
STATE OF CALIFORNIA



SEAL

COUNTY SURVEYOR'S CERTIFICATE  
THE CORNER RECORD WAS RECEIVED 5/12 19 88  
AND EXAMINED AND FILED BY: [Signature]  
TITLE: \_\_\_\_\_  
DOCUMENT No. \_\_\_\_\_  
STATEMENT ON BACK OF SHEET YES  NO