

Index File No. _____

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)


Tract or Survey No. _____

Cor. No. C-E 1/16
Sec. 1 (29)

T 8S R. 22E R.D. Minerals County Madera
Merid. M.D.B. & M. N.F. Sierra State CA

44/43-49

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

none

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

none

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Madera County Road 274 and USFS Road 8S64 (Old Central Camp Road), westerly along 8S64 for approximately 1950' to the posted line, thence north along line for approximately 950' to the corner.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature R. Seaman Title LS 5339

Division _____ Headquarters _____ Date 2/17/95 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a standard USFS aluminum monument
2 1/2" O.D. X 30" long with a 3/2" diameter
cap in a rock mound.

CAP MARKED:

C-E
1/16
LS 5339
1995

ACCESSORIES: DESCRIBE NEW BY'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

1. A 6" diameter Live Oak, blazed and scribed "NBT" bears S27°54'W, 15.13'.
2. A 9" diameter Live Oak, blazed and scribed "NBT" bears N46°01'W, 18.31'.
3. A 9" diameter Live Oak, blazed and scribed "NBT" bears S81°39'E, 66.82'.
4. A 5/8" diameter steel bar with Aluminum Cap, LS 2737, bears S12°38'58"E, 2.77'.

Work Done By R. Seaman Title L.S. Date 2/2/95 State Registration No. 5339
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
Bearings are to the center of the trees, distances are horizontal to a nail and tag
LS 5339 driven into the side center of the root crown. Posted USFS monument and bearing
tree signs as required.