


T 8S R 22E R.D. Minarets County Madera
 Merid. M.D.B. & M. N.F. Sierra State CA 44/43-49



DESCRIBE CORNER MONUMENT FOUND

Found a 2" diameter Iron Pipe with pipe cap stamped appropriately for corner. Pipe leaning over set in a rock mound. Reset pipe at center of rock mound. Accepted a perpetuation of original corner.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1. Found 16" diameter Black Oak, possible regrowth, N54°48'W, 31.97' (6" diameter Black Oak, N54°30'W, 29.04') (GLO).
2. Found 23" diameter Black Oak, S85°18'W, 39.09', (3" diameter Black Oak, S86°W, 29.60') (GLO).

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estob. By _____
 Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Madera County Roads 221 and 222, proceed easterly along Road 222 for approximately 28000' to driveway to South, "Musick", driveway is old railroad grade. Southerly along drive for approximately 1000' to the corner.

Signature: *[Handwritten Signature]* Title: LS 5339 Division: _____ Headquarters: _____ Date: 1/13/95 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Reset Iron Pipe at center of rock mound.
 Rebuilt rock mound.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

3. A 10" diameter Black Oak, blazed and scribed "NBT" bears S15°33'W, 23.17'.
4. Set a steel post with USFS signs 54-5 and 54-9 S45°E, 4'.

Work Done By: R. Seaman Title: L.S. Date: 1/9/95 State Registration No. or Agency: 5339

Certified Cor. Record Prepared? Yes No Filed At: _____ Date: _____

REMARKS

Bearings to center face of all trees, horizontal distance to nail and tag LS 5339, set at side center of all trees. NBT posted with USFS signs 54-3 and 54-9.