	CORNER RECORD (SEARCH) Tract or Cor.]	NW Sec. 3
File No T8S R22E	- (Ref. FSM 7151.4) Survey No. No. R.D. Mingrets Bass (Accounty Madera	4·
Merid. M.D.B.& M.	N.F. Sierra State CA	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
	Found 2" diameter GLO brass cap on a 12" diameter Iron P	line with
	a 2' x 3' rock mound 2' west of Corner. Cap stamped appr	opriately
S33 S34	1917. Accepted as corner.	· princery
T7S R22E		1
T8S Y	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	2
S4 S3 HOTO IDENTIFICATION DATA	1. Found 30" diameter Ponderosa Pine with legiable scrib N22°05'W, 99.66' to a set nail and tag LS 5339 at side of tree. (28" diameter Yellow Pine, N22°30'W, 100.32' corner is 200'± west of drainage (198') (GLO).	center
• .	No other evidence found.	
Photo No		
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH	3
dent. By	From the Teaford Fetaton Subdivision ass as new 1002	CORNER
Signature 7	From the Teaford Estates Subdivision off of Road 223, pre- easterly to end of Moic Drive, thence northerly along wa	oceed
LANE COORDINATE POSITION DATA	access road. NE corner of subdivision is 150'± norther1	rer cank
tate Zone	water tank. Thence East 1320't to corner. Corner lies on	y UI 'a N-C
	spur ridge in dense manzanita.	מ ואדט
-A-L P		
stob. By	3	
(CORNER RECORD (PERPETUATION)	
MONITALENT DECEDIBE NEW MONTH	WENT SET UD MUDK UUNE IV DBEGEONE EAIGTING MUNIIMENT	
•	MENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	
Brushed area around mon		
Brushed area around mon		9 NCE
Brushed area around mon ACCESSORIES DESCRIBE NEW BT 40" diameter Ponderosa	onument. The witness objects etc. established, or work done to preserve existing evidence and the evidence evidence and the evidence evidence evidence and the evidence evi	9 NCE
Brushed area around mon	onument. The witness objects etc. established, or work done to preserve existing evidence and the evidence evidence and the evidence evidence evidence and the evidence evi	9 NCE
Brushed area around mon	onument. The witness objects etc. established, or work done to preserve existing evidence and the evidence evidence and the evidence evidence evidence and the evidence evi	9 NCE
Brushed area around mon	onument. The witness objects etc. established, or work done to preserve existing evidence and the evidence evidence and the evidence evidence evidence and the evidence evi	9 NCE
ACCESSORIES DESCRIBE NEW BT 40" diameter Ponderosa 8" diameter Black Oak	onument. The witness objects etc. established, or work done to preserve existing evidence in Pine, bears N78°28'E, 114.18'. The bears S21°16'W, 20.95'.	9 NCE
Brushed area around mon	onument. The witness objects etc. established, or work done to preserve existing evider a Pine, bears N78°28'E, 114.18'. The property of the preserve existing evider a pine, bears S21°16'W, 20.95'.	9 VCE
Brushed area around mon ACCESSORIES DESCRIBENEW BT 40" diameter Ponderosa 8" diameter Black Oak	witness objects etc. established, or work done to preserve existing evider a Pine, bears N78°28'E, 114.18'. bears S21°16'W, 20.95'. Tille L.S. Dote 12/9/95 State Registration No. 5339 Yes (No) Filed At: Date	9 NCE 10
ACCESSORIES DESCRIBE NEW BTO 40" diameter Ponderosa 8" diameter Black Oak Work Done By R. Seaman Certified Cor Record Prepared? Brushed from corner to a Distance is to nail and	Title L.S. Dote 12/9/95 Stole Registration No. 5339 Yes (No) Filed At: REMARKS all trees. Bearing measured to center face of trees and Horling "LS 5339", at side center of trees. Attached USFS sign	io 11 cizontal
ACCESSORIES DESCRIBENEW BT. 40" diameter Ponderosa. 8" diameter Black Oak Work Done By R. Seaman Certified Cor Record Prepared? Brushed from corner to a	Title L.S. Dote 12/9/95 Stole Registration No. 5339 Yes (No) Filed At: REMARKS all trees. Bearing measured to center face of trees and Horling "LS 5339", at side center of trees. Attached USFS sign	io 11 cizontal
ACCESSORIES DESCRIBE NEW BTO 40" diameter Ponderosa 8" diameter Black Oak Work Done By R. Seaman Certified Cor Record Prepared? Brushed from corner to a Distance is to nail and	Title L.S. Dote 12/9/95 Stole Registration No. 5339 Yes (No) Filed At: REMARKS all trees. Bearing measured to center face of trees and Horling "LS 5339", at side center of trees. Attached USFS sign	10 11 Cizontal
ACCESSORIES DESCRIBE NEW BTO 40" diameter Ponderosa 8" diameter Black Oak Work Done By R. Seaman Certified Cor Record Prepared? Brushed from corner to a Distance is to nail and	Title L.S. Dote 12/9/95 Stole Registration No. 5339 Yes (No) Filed At: REMARKS all trees. Bearing measured to center face of trees and Horling "LS 5339", at side center of trees. Attached USFS sign	io 11 cizontal
ACCESSORIES DESCRIBE NEW BTO 40" diameter Ponderosa 8" diameter Black Oak Work Done By R. Seaman Certified Cor Record Prepared? Brushed from corner to a Distance is to nail and	Title L.S. Dote 12/9/95 Stole Registration No. 5339 Yes (No) Filed At: REMARKS all trees. Bearing measured to center face of trees and Horling "LS 5339", at side center of trees. Attached USFS sign	io 11 cizontal