


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 82



West 1/4 corner of section 9 8/22

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" I.P. up 0.7' & open in rock mound
(Gentry May, 1966 not recorded)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

Dead 20" Oak (Original B.T.) parcial remains
 N 4° 11' 56" E, 99.21' to a P.K. in 11' x 8'
 natural fracture X shaped (N'LY) creek
 N 45° 11' 58", 345.61' to a PK nail in a 7'x4'x7'
 granite outcrop on N/S creek
 West, 33.8' to 30d nail on N/S 20" Blue Oak (K)
 S 31° W, 15.47' to 30d nail on N/S (& up 1.8')
 17" Blue Oak (K)

Copied from P.M. 2156 for Morris
 Surveyed by Breadahl L.S. 4509

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
 STATEMENT ON BACK OF SHEET: YES NO