


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: 2.20 19 71



N 1/4 COR. SECTION 12 8/22

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

F.D. 1 1/4" PIPE BRASS CAPPED MON. - L.S. 1969 IN ROCK MD.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

PINE STUMP N 41° ± W 42.90' ± (ORIG. B.T.)
24" YELLOW PINE S 86° 30' W 7.0' MARKED
"B.T." ON WEST SLOPE
(W.O.G. MISC. BK 1-8)
7-5-58

Fd. 1 1/4" PIPE & B.C. UP 4" IN SMALL ROCK MD. FROM WHICH BEARS:

25" YELLOW PINE S 87° 34' W 7.2'
10" BLACK OAK S 21° E 56.2'
36" YELLOW PINE N 30° 19' E 39.8'

COPIED FROM W.O. GENTRY CORNER TIE TAG 523/48

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 ____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 ____

AND EXAMINED AND FILED _____ 19 ____

BY: _____

TITLE: _____

DOCUMENT No: _____ STATEMENT ON BACK OF SHEET: YES [] NO []