| CORNE | R RECORD |
|--|---------------------------------------|
| COUNTY OF MADERA TOWNSHIP SOUTH, F | RANGE 22 EAST, M.D.B.EM. CALIFORNIA |
| | RANCHO . CONTROL OTHER . |
| CORNER IDENTIFICATION - DATE OF VISIT: APR 2 | 9 19 20 |
| | |
| CORNER - LEFT AS FOUND FOUND AND TAGGED REE | STABLISHED OBLITERATED CORNER REBUILT |
| PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND ME | |
| _ | |
| IRON PIPE IN MO. | UND |
| • | • |
| PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUA: | TED |
| | |
| | |
| | • |
| ALIFORNIA COORDINATE SYSTEM ORDER: FIRST | SECOND THIRD |
| TATIONS USED: NGS (USC & GS) STATE | COUNTY OTHER STATION STATION |
| ONE ELEVATION NORT | THINGS (Y) EASTINGS (X) |
| | ESTINGS (X) |
| 2 ORIGINAL BEARING | MEES IN PLACE |
| | |
| | |
| | |
| | |
| | · |
| | |
| | |
| | |
| | · |
| COPIED FROM OLD MADERA COUNT | Y GOVERNMENT MONUMENTS BOOK. |
| JO RUE | |
| SURVEYOR'S CERTIFICATE | COUNTY SURVEYOR'S CERTIFICATE |
| IS COPNER RECOPD WAS PREPARED BY ME OR UNDER MY | THE CORNER RECORD WAS RECEIVED 19 |
| RECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S | AND EXAMINED AND FILED 19 |
| 19 | |
| SIGNED: | BY: |
| or R.C.E. No. | TITLE: |

SEAL

DOCUMENT NO: UTATEMENT ON BACK OF SHEET: YES