## CORNER RECORD

| COUNTY OF MADERA TOWNSHIP & SOUTH,   | RANGE 22 EAST, M.D.B.&M. CALIFORNIA  |
|--|--|
| CORNER TYPE: GOV'T. CORNER MEANDER   | RANCHO . CONTROL OTHER .   |
| CORNER IDENTIFICATION - DATE OF VISIT: MAY   |  |
| CORNER - LEFT AS FOUND   FOUND AND TAGGED   RE   | ESTABLISHED OBLITERATED CORNER REBUILT   |
| PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND M   | ETHOD USED TO IDENTIFY OR REESTABLISH  |
| IRON PIPE IN   | MOUND.   |
| PHYSICAL DESCRIPTION OF MANUFACTOR PROPERTY  | The state of the s |
| PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUR  | ATED   |
|  |  |
|  |  |
| CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  | SECOND THIRD   |
| STATIONS USED: NGS (USC & GS) STATE  |  |
| ZONE ELEVATION NOR   | THINGS (Y) EASTINGS (X)  |
|  |  |
| SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REAL   | ARKS AND TOPO OF AREA)   |
| 1- ORIGINAL BEARING  | TREE   |
|  |  |
|  |  |
|  |  |
|  | ·  |
|  | •  |
|  |  |
|  |  |
|  |  |
|  |  |
| COPIED FROM OLD MADERA COUN  | TY GOVERNMENT MONUMENTS BOOK.  |
|  | JO RUE   |
| SURVEYOR'S CERTIFICATE   | COURTY CURVEYORL   |
| HIS COPNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S | COUNTY SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED 19  |
| CT ON19  | AND EXAMINED AND FILED 19  |
| SIGNED:  | ВУт  |
| S. or R.C.E. No.   | TITLE:   |

SEAL

DOCUMENT NO: STATEMENT ON BACK OF SHEET: YES

ио 🔲