COUNTY OF MADERA T. 85 R. 77E MD MERIDIAN CALIFORNIA
COUNTY OF MADERA T. 8 S R. 178 MD MERIDIAN CALIFORNIA CORNER TYPE: GOV'T. CORNER MEANDER 7-7 RANCHO CONTROL OTHER CONTROL OTHER CONTROL 1976
514 COR SEC. 72, TBS, RXXE
22 S/4 COR SEC. 72, TBS, RAZE N/4 COR SEC 27 " "
CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
FOUND 3" IRON PIPE UP 48". TIES TO PREVIOUS SURVEYS BY MADERA COUNTY
AND OTHERS VERIFIED LOCATION. MADERA COUNTY KOAD DEPT. SUPERVISOR
FOUND 3" IRON PIPE UP 48". TIES TO PREVIOUS SURVEYS BY MADERA COUNTY AND OTHERS VERIFIED LOCATION. MADERA COUNTY ROAD DEPT. SUPERVISOR TESTIFIED HE ASSISTED IN SETTING EXISTING PIPE FENCE POST OVER ORIGINAL CORNER MONUMENT.
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
SET A 2" BRASS CAP INSIDE EXISTING PIPE MONUMENT. SET SHINNERS IN WITNESS TREES.
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION STATI
SKETCH: (Include reference tie or witness points, remarks and topo of area)
MADERA COUNTY RD. DEPT. MAINTENENCE YARD
MAINTENENCE YARD
ENTRANCE
OLD NORTH FORK ROAD - REPLACED BY RD. 200 36" BLUE OAK NIBBE
JOB NOICH 36" BLUB OAK
00 0 Mon. N88E
491 FEET
30" BUE OAK
S86 W
SBG W LAND SUD FEET
SURVEYOR'S CERTIFICATE COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY THE CORNER RECORD WAS RECEIVED 7-12 1926 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT AND EXAMINED AND FILED 1976
ON JULY 1128 1 1976 BY: Jore B. Milan Title: Civil Engr. Asst.
L.S. or R.C.E. No.: DOCUMENT No. 76-16-4
STATEMENT ON BACK OF SHEET

SEAL

YES 🔲

NO 📜