


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 8 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: Feb. 19 84



W 1/4 cor. Sec. 22 8/22

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1 1/2" I.D. I.P. W/ BRASS CAP TAGGED
L.S. 4126 UP 0.7' IN CAIRN

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

S 12° W 15.90' TO A PK NAIL
IN 1.5' x 1.3' x FLUSH ROCK

NORTH 1.35' TO A 30d GALV. NAIL
ON W/SIDE 3" LIVE OAK

1.7' W OF & 0.5' N OF ANGLE PT.
IN FENCE TO SOUTH & EAST

COPIED FROM RIS 84-18 FOR
MILLER BY Breadahl

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

_____ 19 _____

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____

AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT NO: _____
STATEMENT ON BACK OF SHEET: YES [] NO []